

Issues


SERVICE BULLETIN No. BB/37, BB-S/3, AB18

- 1. WITH REFERENCE TO:** Hot-air balloons meeting these criteria:
- Kubicek BB and BB-S balloons operated with Aerotechnik baskets J1 and J2 and/or fuel cylinders S23
 - All Aerotechnik AB, AB2 and AB8 balloons
- Balloons registered in the USA are not affected.
- 2. REASON:** Renewal of the range of approved combinations of Kubicek envelopes with Aerotechnik bottom ends and Aerotechnik envelopes with Kubicek bottom ends.
- 3. REQUIRED ACTION:** Update the manuals to the latest approved revision:
- For all Aerotechnik envelopes and Kubicek BB and BB-S envelopes of serial numbers up to 639:
- Flight Manual (*doc. no. B.0102, revision 19*)
 - Maintenance Manual (*doc. no. B.0202, revision 13*)
- For Kubicek BB and BB-S envelopes of serial numbers 640 and higher:
- Flight Manual Supplement Older Equipment (*doc. no. B.2102-OBFF, revision 4*)
 - Maintenance Manual (*doc. no. B.2202, revision 3*)
- 4. DEADLINE FOR ACTION:** 31 May 2010
- 5. ACTION CARRIED OUT BY:** Owner / operator
- 6. INDUCED COST COVERED:** Owner / operator – only the cost of print
- 7. NECESSARY MATERIAL:** The above mentioned manuals
- 8. PROCESS:** Download the respective documents for the Kubicek Balloons website, print them and replace the manuals originally supplied by the new edition.
- 9. BULLETIN TAKES EFFECT:** 11 May 2010
- 10. ENCLOSURES:** None

Technical content of this document is approved under the authority of DOA No. EASA.21J.277.

On behalf of BALÓNY KUBÍČEK spol. s r.o.

Petr Kubíček, technical director



Date: 11 May 2010