

Issues


SERVICE BULLETIN No. BB/44

- 1. WITH REFERENCE TO:** Kubicek BB balloons of envelope serial numbers: 1010, 1012, 1013, 1014, 1015, 1016.
- 2. REASON:** An information on obligation to report service difficulties, suggestions and comments introduced.
- 3. REQUIRED ACTION:** Update the Flight Manual and the to the recent revision.
- 4. DEADLINE FOR ACTION:** 30 Nov 2013
- 5. ACTION CARRIED OUT BY:** Owner / operator
- 6. INDUCED COST COVERED:** Owner / operator
- 7. NECESSARY MATERIAL:** Flight Manual (*doc. no. B.0102, revision 19*)
- 8. PROCESS:** Download the respective document from the Kubicek Balloons website, print it and replace the manual originally supplied by the new revision.
- 9. BULLETIN TAKES EFFECT:** 09 Oct 2013
- 10. ENCLOSURES:** None

Technical content of this document is approved under the authority of DOA No. EASA.21J.277.

On behalf of BALÓNY KUBÍČEK spol. s r.o.

Petr Kubíček, technical director



Date: 09 Oct 2013