

Issues

## SERVICE BULLETIN No. 53

- 1. WITH REFERENCE TO:** **All hot air balloons Kubicek and Aerotechnik**  
(EASA TC No. EASA.BA.001, EASA.BA.002, EASA.BA.003, EASA.BA.004 and EASA.BA.017)
- 2. REASON:** This bulletin is issued based on the feedback from the owners, operators and repairmen who asked for a checklist covering all points of Annual/100 hrs inspection. For that reason, the whole procedure of Annual/100 hrs inspection was revised and updated as well as the check list was introduced in the latest revision of Kubicek Maintenance Manual.
- 3. REQUIRED ACTION:** Update the maintenance manual to the latest approved revision:
  - Maintenance Manual edition 3 - Document No. B.3202 rev. 1
  - Maintenance Manual edition 3 - Document No. B.3205 rev. 1 (balloons registered in the USA)
- 4. DEADLINE FOR ACTION:** **Till next annual/100 hrs inspection**
- 5. ACTION CARRIED OUT BY:** Approved maintenance individual/organization
- 6. INDUCED COST COVERED:** None
- 7. NECESSARY MATERIAL:** The above mentioned manuals downloadable from <https://www.kubicekballoons.eu/technical-support/manuals>
- 8. PROCESS:** The personal performing Annual/100 hrs inspection shall follow the updated procedure supported by the new checklist.
- 9. BULLETIN TAKES EFFECT:** **February 3, 2019**
- 10. ENCLOSURES:** None

Technical content of this document is approved under the authority of DOA No. EASA.21J.277.



On behalf of BALÓNY KUBÍČEK spol. s r.o.

Petr Kubíček, Head of Design Organisation

Date: **February 05, 2019**