

issues

MANDATORY BULLETIN No. BB/21a, AB014a

- 1. WITH REFERENCE TO:**
1. Change of the Flight Manual
 - a) All of the hot air balloons manufactured by 114 (714) ZO Svazarmu, Aerotechnik, Aerotechnik p.o.s. and Aerotechnik s.r.o.
 - b) All of the hot air balloons manufactured by Kubíček spol. s r.o. and BALÓNY KUBÍČEK spol. s r.o. except special shaped balloons.
 2. Change of The Maintenance Manual
 - a) All of the hot air balloons manufactured by 114 (714) ZO Svazarmu, Aerotechnik, Aerotechnik p.o.s. and Aerotechnik s.r.o.
 - b) All of the hot air balloons manufactured by Kubíček spol. s r.o. and BALÓNY KUBÍČEK spol. s r.o. except special shaped balloons.
- 2. REASON:**
- 1) Extension of the BB type with the new BB20 GP envelope
 - 2) Change of the operational limitations
- 3. REQUIRED ACTION:** Change of the relevant sheets of the Flight Manual and Maintenance Manual concerning all translations
- 4. DEADLINE FOR ACTION:** Immediately after this bulletin receiving
- 5. ACTION CARRIED OUT:** Balloon operator
- 6. INDUCED COST COVERED:** None
- 7. NECESSARY MATERIAL:** None
- 8. PROCESS:**
- 1) Cancel the relevant sheets of the present manuals
 - 2) Insert the new ones (Issue 1.7.2002)
- 9. BULLETIN TAKES EFFECT:** From the date of the CAA, Czech Republic approval.

10. ENCLOSURES:1) Flight Manual

Sheets: 0-(i)/(ii)

1-3/4, 7/ILB

2-1/2, 3/4, 5/6, 7/8, 9/10

5-1/2, 3/4

6-1/2, 3/4

7-1/2

1) Maintenance Manual

Sheets: 0-(i)/(ii)

3-3/4

4-1/2, 3/4

6-3/4

*On behalf of the manufacturer:**Ing. Josef Pučégl**Date: 1.7.2002*